From: Customer Request <custreq@facil.umass.edu>

Sent:Monday, April 23, 2012 1:26 PMTo:servdesk@facil.umass.eduCc:Hanchett, James (DPH)

Subject: FW: WReq Entry for Morrill I on Monday, April 23, 2012 - 13:17

Please create a service call work order for the zone maintenance. Thanks

----Original Message-----

From: webadmin@oit.umass.edu [mailto:webadmin@oit.umass.edu]

Sent: Monday, April 23, 2012 1:18 PM

To: custreq@facil.umass.edu

Subject: WReq Entry for Morrill I on Monday, April 23, 2012 - 13:17

The results of this submission may be viewed at:

https://www.umass.edu/af-forms/node/9/submission/6041

Submitted on Monday, April 23, 2012 - 13:17 by hanchett

--Requester Information--

Netid (hidden): hanchett

Request Date (hidden): Monday, April 23, 2012 - 13:15

First & Last Name: Jim Hanchett Department: Mass Public Health

Mailing Address: Room N251 Morrill I 637 N Pleasant St. Amherst, MA 01003

Email: james.hanchett@state.ma.us

Phone Number: 5452607

Fax: 5452608

--Work Request Information--Building Requiring Work: Morrill I Room Number/Location: Room N236

Describe Work Requested: Exhaust blower is not working.

Morrill I Room N236, Exhaust blower is not working., Jim Hanchett, Phone:

5452607, Fax: 5452608